

Work Order ID 66364



Page 1

Friday, February 11, 2011 1:18:09 PM

Item ID: D206-642-511

Accept



Setup Start



Revision ID:

Item Name: Float Skidtube LH

Stop



Start Date: 2/14/2011 Start Qty: 1.00



Cust Item ID:

Required Date: 2/28/2011 Req'd Qty: 1.00



Customer:

Reference:

Approvals: Process Plan: MF

Date: 11-02-11

Tooling:

Date:

Run Start



QC:

Date:

SPC (Y/N):

Date:

Stop



Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

Draw Nbr

Revision Nbr

INN-D206-642

Rev M

100

0.00



DOCUMENT CONTROL

DC

Memo

0.00

Document Control

Photocopy bluefile and create labels per PPP D206-642-511CHG004

8 u l o 6 l o 0

for BG 11-6-7 (3)

110

0.00



Pick Kit

Packaging

Memo

0.00

Packaging

P

120

0.00



QC4- 100% Inspect kits for completeness

QC

Memo

0.00

Quality Control

8 u l o 6 l o 0

(70)

1366360

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Work Order ID 66364

Page 2

Friday, February 11, 2011 1:18:09 PM

Item ID: D206-642-511

Accept



Setup Start



Revision ID:

Stop



Item Name: Float Skidtube LH

Start Date: 2/14/2011 Start Qty: 1.00



Cust Item ID:

Required Date: 2/28/2011 Req'd Qty: 1.00



Customer:

Reference:

Run Start



Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____

Stop



QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
130 Packaging	Packaging	0.00							
Packaging	Memo	0.00							
Packaging	Identify and pack for shipping as per PPP D206-642-511 Location: _____ <i>F</i>								
140 QC	QC21- Final Inspection - Work Order Release	0.00							
Quality Control	Memo	0.00							

11/06/11
MS
11-08-09

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

Friday, February 11, 2011 1:18:07 PM

Page 1

Work Order ID: 66364

Parent Item: D206-642-511

Parent Item Name: Float Skidtube LH



Start Date: 2/14/2011

Required Date: 2/28/2011

Start Qty: 1.00

Required Qty: 1.00

Comments: IPP Rev:B 05.09.23 Revised per D206-642 Rev. J KJ/JLM
 IPP Rev:C 07-02-23 As per IIN D206-642 Rev K JLM
 IPP rev D 07.06.06 added K642-511 EC
 IPP Rev:E 07-12-05 ECN 1080p Rev L DD verified by:

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D206-642-541 Replacement Skidtube		Manufactured	No			120	Each	1.0000	1	1			
<div> <div>Location</div> <div>FG073</div> <div>34772</div> </div> <div> <div>Loc Qty</div> <div>1</div> <div>1</div> </div> <div> <div>Loc Code</div> <div></div> <div></div> </div>													
K642-511 <i>CHGUBD</i> saddle kit 642-511		Manufactured	No			120	Each	0.0000	1	1			

66364

67007

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries